

**TABLE D—STANDARD PRESSURE RANGES**

**English Units**

Pressure Code <sup>(1)</sup>	Pressure Range	Displayed Units <sup>(2)</sup>	Resolution	Maximum Overpressure
01E	0-0.1 in. H <sub>2</sub> O	.100	0.001"	5.0"
02E	0-0.2 in. H <sub>2</sub> O	.200	0.001"	5.0"
04E	0-0.5 in. H <sub>2</sub> O	.500	0.001"	5.0"
05E	0-1.0 in. H <sub>2</sub> O	1.000	0.001"	20.0"
06E	0-2.0 in. H <sub>2</sub> O	1.999	0.001"	20.0"
08E	0-5.0 in. H <sub>2</sub> O	5.00	0.01"	5 psid
09E	0-10.0 in. H <sub>2</sub> O	10.00	0.01"	5 psid
11E	0-20.0 in. H <sub>2</sub> O	19.99	0.01"	5 psid
15E	0-1 psid	1.000	0.001"psid	15 psid
16E	0-2 psid	1.999	0.001"psid	15 psid
17E	0-3 psid	3.00	0.01"psid	15 psid
18E	0-5 psid	5.00	0.01"psid	15 psid
19E	0-15 psid	15.00	0.01"psid	30 psid
20E	0-30 psid	30.0	0.1"psid	60 psid
**E	Contact factory for other pressure ranges, displayed units and resolution			

**Metric Units, millimeters of water**

Pressure Code <sup>(1)</sup>	Pressure Range	Displayed Units <sup>(2)</sup>	Resolution	Maximum Overpressure
01M	0-2.50 mm H <sub>2</sub> O	2.50	0.01 mm	125 mm
02M	0-5.00	5.00	0.01 mm	125 mm
04M	0-10.0	10.00	0.01 mm	125 mm
05M	0-25.0	25.0	0.1 mm	500 mm
06M	0-50.0	50.0	0.1 mm	500 mm
08M	0-100	100.0	0.1 mm	3.5 m
09M	0-250	250	1.0 mm	3.5 m
11M	0-500	500	1.0 mm	3.5 m
13M	0-1.00 meter	1.000	.001 meter	10 m
14M	0-2.50 meter	2.50	.01 meter	10 m
15M	0-5.00 meter	5.00	.01 meter	10 m
16M	0-10.0 meter	10.00	.01 meter	20 m
17M	0-20.0 meter	19.99	.01 meter	40 m
**M	Contact factory for other pressure ranges, displayed units and resolution			

**Metric Units, pascals**

Pressure Code <sup>(1)</sup>	Pressure Range	Displayed Units <sup>(2)</sup>	Resolution	Maximum Overpressure
01P	0-25 Pa	25.0	0.1 Pa	1.25 kPa
02P	0-50 Pa	50.0	0.1 Pa	1.25 kPa
04P	0-100 Pa	100.0	0.1 Pa	1.25 kPa
05P	0-250 Pa	250	1 Pa	5.0 kPa
06P	0-500 Pa	500	1 Pa	5.0 kPa
08P	0-1.0 kPa	1.000	1 Pa	35 kPa
09P	0-2.5 kPa	2.50	10 Pa	35 kPa
11P	0-5.0 kPa	5.00	10 Pa	35 kPa
13P	0-10 kPa	10.00	10 Pa	100 kPa
14P	0-25 kPa	25.0	100 Pa	100 kPa
15P	0-50 kPa	50.0	100 Pa	100 kPa
16P	0-100 kPa	100.0	100 Pa	200 kPa
17P	0-200 kPa	199.9	100 Pa	400 kPa
**P	Contact factory for other pressure ranges, displayed units and resolution			

(1) Use this code when ordering.

(2) This column shows the number of digits that are displayed and the position of the decimal point.